







# PWR Air




Quick Guide  
Guide Rapide








## Preparation | Préparation














## Prophy Powder | Poudre



## Perio Powder | Poudre





**APAIRPOL**

<https://hufriedygroup.com/en/company/faq>

**PWR Air**  
Quick Guide  
Guide Rapide

**HuFriedyGroup**  
The Best In Practice

All company and product names are trademarks of Hu-Friedy Mfg. Co., LLC, its affiliates or related companies, unless otherwise noted. Marks not registered in all jurisdictions. ©2026 Hu-Friedy Mfg. Co., LLC. All rights reserved.

**Hu-Friedy**

Manufactured for / Fabriqué pour:  
Hu-Friedy Mfg. Co., LLC  
3232 N. Rockwell Street  
Chicago, IL 60618 | USA  
1-800-Hu-Friedy | HuFriedyGroup.com

02150844 - Quick Guide - PWR AIR  
REV 00 - 13/01/2026