


High Volume Evacuator (HVE) Tips

REF ZET / ZETNV / ZES50

INSTRUCTIONS FOR USE

1. Attach tip to High Volume Evacuator (HVE) hand piece, ensuring that the preferred working end is not inserted into the valve.
2. Dispose properly when procedure is finished.



CROSSTEX



Crosstex International, Inc.
6789 W. Henrietta Road, Rush, NY 14543 USA
585.359.0130 | 631.582.6777 | HuFriedyGroup.com



MDSS GmbH
Schiffgraben 41
30175 Hannover, Germany



Not made with natural rubber latex

Made in USA

ZE-IFU-EN / REV C - 03/2022

In case of any serious incident that has occurred and involves our devices within the European Union, please report it to Hu-Friedy Mfg. Co., LLC and your national competent authority of the member state.

All company and product names are trademarks of Hu-Friedy Mfg. Co., LLC, its affiliates or related companies, unless otherwise noted.

©2026 Hu-Friedy Mfg. Co., LLC. All rights reserved.